



SECTOR GUAM



ATOSSCOM

July 31, 2019



Homeland
Security

United States
Coast Guard





NIPPON MARU Allision





FUKUICHI MARU No.112




| 船舶発生廃棄物記録簿 RECORD OF GARBAGE DISCHARGES | | | | | | | |
|--|--|---|---|--------------------------------|---|---|--------------------------------------|
| 船名 第112福一丸 Ship's Name : 第112福一丸 | | 船籍国/船主 Country of Origin/Owner : J/T/S | | IMO番号 IMO No. : 9008736 | | 期間 から まで Period from to | |
| 日時 Date/Time | 船舶の位置/備考 (事故による排出に関する事項等) Position of the Ship/Remarks (e.g. accidental loss) | 廃棄物の種類 Category | 排出され、又は焼却 される廃棄物の数量 Estimated amount discharged or incinerated (m³) | 排出される 廃棄物の数量 To sea (m³) | 受入施設へ 排出される 廃棄物の数量 To Reception Facility (m³) | 焼却される 廃棄物の数量 Incineration (m³) | 証明/署名 Certification/ Signature |
| 4/1 12 ⁰⁰ | 27-36N 142-20E | 13 | | 0.016m³ | | | 津田 |
| 4/13 12 ⁰⁰ | 26-36N 141-19E | 13 | | 0.016m³ | | | |
| 4/11 12 ⁰⁰ | 26-49N 149-34E | 13 | | 0.016m³ | | | |
| 4/13 12 ⁰⁰ | 22-32N 148-27E | 13 | | 0.016m³ | | | |
| 4/18 07 ⁰⁰ | 琉球諸島入港 | | | | | | |
| 3/14 07 ⁰⁰ | 出港 | | | | | | |
| 3/16 12 ⁰⁰ | 21-02N 138-37E | 13 | | 0.020m³ | | | 津田 |
| 3/18 12 ⁰⁰ | 16-20N 138-48E | 13 | | 0.020m³ | | | |
| 3/20 12 ⁰⁰ | 06-42N 139-11E | 13 | | 0.020m³ | | | |
| 3/22 12 ⁰⁰ | 00-40S 149-38E | 13 | | 0.025m³ | | | |
| 3/24 12 ⁰⁰ | 00-40S 152-20E | 13 | | 0.020m³ | | | |
| 3/26 12 ⁰⁰ | 00-18S 152-01E | 13 | | 0.016m³ | | | |
| 3/28 16 ⁰⁰ | 01-53N 151-38E | 13 | | 0.025m³ | | | |

船長の署名 大瀬 稔
Master's Signature : 大瀬 稔 Date : 3/28





Heavy Weather Events



Top Left: Weather Underground, <https://www.wunderground.com/cat6/Category-5-Super-Typhoon-Yutu-Pounding-US-Northern-Mariana-Islands>

Top Right: LCDR J.J. Schock, Bottom Left: Commonwealth Ports Authority, Bottom Right: Port Authority of Guam



Questions?



Join us for a Tour!
Sign up for the Port of Guam tour on Friday
Morning!

CG Facilities Inspectors and Port Authority of
Guam staff will be there to answer questions!